

Fundamentals of Machining/Orthogonal Machining

Chapter 20

20.1 Introduction




FIGURE 20-1 The fundamental inputs and outputs to machining processes.

20.2 Fundamentals





FIGURE 20-2 The seven basic machining processes used in chip formation.

FIGURE 20-3 Turning a cylindrical workpiece on a lathe requires you to select the cutting speed, feed, and depth of cut.



Turning, Single Point and Box Tools

Material	Hard- ness	Condition	Depth of Cut* in mm	High Speed Steel Tool			Carbide Tool							
				Speed	Feed	Tool Material AISI ISO	Uncoated		Coated					
							Speed		Feed	Tool Material Grade C ISO	Speed	Feed	Tool Material Grade C ISO	
							Brazed	Index- able						lpm m _s /min
L. FREE MACHINING CARBON STEELS, WROUGHT (cont.) Medium Carbon Leaded (cont.) (materials listed on preceding page)	225	Hot Rolled,	.040	160	.008	M2, M3	500	650	.007	C-7	925	.007	CC-7	
		Normalized,	.150	125	.015	M2, M3	390	480	.020	C-6	600	.015	CC-6	
		Annealed,	.300	100	.020	M2, M3	310	375	.030	C-6	500	.020	CC-6	
		Cold Drawn	.625	80	.030	M2, M3	240	290	.040	C-6	—	—	—	
		or	1	49	.20	S4, S5	150	185	.18	P10	230	.18	CP10	
		Quenched	4	38	.40	S4, S5	120	145	.50	P20	185	.40	CP20	
	275	and	8	30	.50	S4, S5	95	115	.75	P30	150	.50	CP30	
		Tempered	16	24	.75	S4, S5	75	88	1.0	P40	—	—	—	
		275 to 325	Hot Rolled,	.040	135	.007	T15, M42 [†]	460	545	.007	C-7	825	.007	CC-7
			Normalized,	.150	105	.015	T15, M42 [†]	350	425	.020	C-6	525	.015	CC-6
			Normalized,	.300	85	.020	T15, M42 [†]	275	380	.030	C-6	425	.020	CC-6
			Annealed	.625	—	—	—	—	—	—	—	—	—	—
	or		1	41	.18	S9, S11 [†]	140	165	.18	P10	250	.18	CP10	
	Quenched		4	32	.40	S9, S11 [†]	105	130	.50	P20	160	.40	CP20	
	325 to 375	and	8	26	.50	S9, S11 [†]	84	100	.75	P30	130	.50	CP30	
		Tempered	16	—	—	—	—	—	—	—	—	—	—	
		325 to 375	Quenched	.040	100	.007	T15, M42 [†]	390	480	.007	C-7	725	.007	CC-7
			and	.150	80	.015	T15, M42 [†]	300	375	.020	C-6	475	.015	CC-6
			and	.300	65	.020	T15, M42 [†]	230	290	.030	C-6	375	.020	CC-6
			and	.625	—	—	—	—	—	—	—	—	—	—
	Tempered		1	30	.18	S9, S11 [†]	120	145	.18	P10	220	.18	CP10	
	Tempered		4	24	.40	S9, S11 [†]	90	115	.50	P20	145	.40	CP20	
	375 to 425	and	8	20	.50	S9, S11 [†]	70	88	.75	P30	115	.50	CP30	
		and	16	—	—	—	—	—	—	—	—	—	—	
375 to 425		Quenched	.040	70	.007	T15, M42 [†]	325	400	.007	C-7	600	.007	CC-7	
		and	.150	55	.015	T15, M42 [†]	250	310	.020	C-6	400	.015	CC-6	
		and	.300	45	.020	T15, M42 [†]	200	240	.030	C-6	325	.020	CC-6	
		and	.625	—	—	—	—	—	—	—	—	—	—	
	Tempered	1	21	.18	S9, S11 [†]	100	120	.18	P10	185	.18	CP10		
	Tempered	4	17	.40	S9, S11 [†]	76	95	.50	P20	120	.40	CP20		
425	and	8	14	.50	S9, S11 [†]	60	75	.75	P30	100	.50	CP30		
	and	16	—	—	—	—	—	—	—	—	—	—		

FIGURE 20-4 Examples of a table for selection of speed and feed for turning. (Source: Metcut's Machinability Data Handbook.)

			16	—	—	—	—	—	—	—	—	—		
2. CARBON STEELS, WROUGHT Low Carbon	85 to 125	Hot Rolled,	.040	185	.007	M2, M3	535	700	.007	C-7	1050	.007	CC-7	
			.150	145	.015	M2, M3	435	540	.020	C-6	700	.015	CC-6	
			.300	115	.020	M2, M3	340	420	.030	C-6	550	.020	CC-6	
		Normalized,	.625	90	.030	M2, M3	265	330	.040	C-6	—	—	—	
	1005 1010 1020 1006 1012 1023 1008 1015 1025 1009 1017	125 to 175	Annexed or Cold Drawn	1	56	.18	S4, S5	165	215	.18	P10	320	.18	CP10
				4	44	.40	S4, S5	135	165	.50	P20	215	.40	CP20
				8	35	.50	S4, S5	105	130	.75	P30	170	.50	CP30
				16	27	.75	S4, S5	81	100	1.0	P40	—	—	—
	125 to 175	Hot Rolled,	.040	150	.007	M2, M3	485	640	.007	C-7	950	.007	CC-7	
			.150	125	.015	M2, M3	410	500	.020	C-6	625	.015	CC-6	
			.300	100	.020	M2, M3	320	390	.030	C-6	500	.020	CC-6	
		Normalized,	.625	80	.030	M2, M3	245	305	.040	C-6	—	—	—	
	175 to 225	Annexed or Cold Drawn	1	46	.18	S4, S5	150	195	.18	P10	290	.18	CP10	
			4	38	.40	S4, S5	125	150	.50	P20	190	.40	CP20	
			8	30	.50	S4, S5	100	120	.75	P30	150	.50	CP30	
			16	24	.75	S4, S5	75	95	1.0	P40	—	—	—	
175 to 225	Hot Rolled,	.040	145	.007	M2, M3	460	570	.007	C-7	850	.007	CC-7		
		.150	115	.015	M2, M3	385	450	.020	C-6	550	.015	CC-6		
		.300	95	.020	M2, M3	300	350	.030	C-6	450	.020	CC-6		
	Normalized,	.625	75	.030	M2, M3	235	265	.040	C-6	—	—	—		
225 to 275	Annexed or Cold Drawn	1	44	.18	S4, S5	140	175	.18	P10	260	.18	CP10		
		4	35	.40	S4, S5	115	135	.50	P20	170	.40	CP20		
		8	29	.50	S4, S5	90	105	.75	P30	135	.50	CP30		
		16	21	.75	S4, S5	72	81	1.0	P40	—	—	—		
225 to 275	Annexed or Cold Drawn	.040	125	.007	M2, M3	410	510	.007	C-7	750	.007	CC-7		
		.150	95	.015	M2, M3	360	400	.020	C-6	500	.015	CC-6		
		.300	75	.020	M2, M3	285	315	.030	C-6	400	.020	CC-6		
	Normalized,	.625	60	.030	M2, M3	220	240	.040	C-6	—	—	—		
225 to 275	Annexed or Cold Drawn	1	38	.18	S4, S5	125	155	.18	P10	250	.18	CP10		
		4	29	.40	S4, S5	100	120	.50	P20	150	.40	CP20		
		8	23	.50	S4, S5	87	95	.75	P30	120	.50	CP30		
		16	18	.75	S4, S5	67	73	1.0	P40	—	—	—		

See section 15.1 for Tool Geometry.


*Caution: Check Horsepower requirements on heavier depths of cut.

See section 16 for Cutting Fluid Recommendations.

†Any premium HSS (T15, M33, M41-M47) or (S9, S10, S11, S12).

FIGURE 20-4 Examples of a table for selection of speed and feed for turning. (Source: Metcut's Machinability Data Handbook.)


FIGURE 20-5 Relationship of speed, feed, and depth of cut in turning, boring, facing, and cutoff operations typically done on a lathe.



Turning


Speed, stated in surface feet per minute (sfpm), is the peripheral speed at the cutting edge. Feed per revolution in turning is a linear motion of the tool parallel to the rotating axis of the workpiece. The depth of cut reflects the third dimension.

$L = \text{length of cut}$
 $T_m = \frac{L + A}{f_r N_s}$




Boring

Enlarging hole of diameter D_1 to diameter D_2 . Boring can be done with multiple cutting tools. Feed in inches per revolution, f_r .



Facing

Tool feeds to center of workpiece so $L = D/2$. The cutting speed is decreasing as the tool approaches the center of the workpiece.




Grooving, parting, or cutoff

Tool feed perpendicular to the axis of rotation. The width of the tool produces the depth of cut (DOC).

TABLE 20-1 Shop Formulas for Turning, Milling, Drilling, and Broaching (English Units)

Parameter	Turning	Milling	Drilling	Broaching
Cutting speed, fpm	$V = 0.262 \times D_t \times$ rpm	$V = 0.262 \times D_m \times$ rpm	$V = 0.262 \times D_d \times$ rpm	V
Revolutions per minute, N_s	$\text{rpm} = 3.82 \times V_c/D_t$	$\text{rpm} = 3.82 \times V_c/D_m$	$\text{rpm} = 3.82 \times$ V_c/D_d	—
Feed rate, in./min	$f_m = f_r \times \text{rpm}$	$f_m = f_r \times \text{rpm}$	$f_m = f_r \times \text{rpm}$	—
Feed per rev tooth pass, in./rev	f_r	f_t	f_r	—
Cutting time, min, T_m	$T_m = L/f_m$	$T_m = L/f_m$	$T_m = L/f_m$	$T_m = L/12V$
Rate of metal removal, in. ³ /min	$\text{MRR} = 12 \times d \times f_r$ $\times V_c$	$\text{MRR} = w \times d \times f_m$	$\text{MRR} = \pi D^2 d/4$ $\times f_m$	$\text{MRR} = 12 \times w \times d$ $\times V$
Horsepower required at spindle	$\text{hp} = \text{MRR} \times \text{HP}_s$	$\text{hp} = \text{MRR} \times \text{HP}_s$	$\text{hp} = \text{MRR} \times$ HP_s	—
Horsepower required at motor	$\text{hp}_m = \text{MRR} \times$ HP_s/E	$\text{hp}_m = \text{MRR} \times$ HP_s/E	$\text{hp}_m = \text{MRR} \times$ HP_s/E	$\text{hp}_m = \text{MRR} \times$ HP_s/E
Torque at spindle	$t_s = 63,030$ hp/rpm	$t_s = 63,030$ hp/rpm	$t_s = 63,030$ hp/rpm	—
Symbols	D_t = Diameter of workpiece in turning, inches D_m = Diameter of milling cutter, inches D_d = Diameter of drill, inches d = Depth of cut, inches E = Efficiency of spindle drive f_m = Feed rate, inches per minute f_r = Feed, inches per revolution f_t = Feed, inches per tooth hp_m = Horsepower at motor MRR = Metal removal rate, in. ³ /min		hp = horsepower at spindle L = Length of cut, inches n = Number of teeth in cutter HP_s = Unit power, horsepower per cubic inch per minute, specific horsepower N_s = Revolution per minute of work or cutter t_s = Torque at spindle, inch-pound T_m = Cutting time, minutes V = Cutting speed, feet per minute w = Width of cut, inches	

Values for specific horsepower (unit power) are given in Table 20-4.



Slab milling – multiple tooth


Slab milling is usually performed on a horizontal milling machine. Equations for T_m and MRR derived in Chapter 25.

The tool rotates at rpm N_s . The workpiece translates past the cutter at feed rate f_m , the table feed. The length of cut, L , is the length of workpiece plus allowance, L_A .

$$L_A = \sqrt{\frac{D^2}{4} - \left(\frac{D}{2} - d\right)^2} = \sqrt{d(D-d)} \text{ inches}$$

$$T_m = (L + L_A)/f_m$$

The MRR = Wdf_m , where W = width of the cut and d = depth of cut.




Face milling
Multiple-tooth cutting

Given a selected cutting speed V and a feed per tooth f_t , the rpm of the cutter is $N_s = 12V/\pi D$ for a cutting of diameter D . The table feed rate is $f_m = f_t n N_s$ for a cutter with n teeth.

The cutting time, $T_m = (L + L_A + L_o)/f_m$ where $L_o = L_A = \sqrt{W(D-W)}$ for $W < D/2$ or $L_o = L_A = D/2$ for $W \geq D/2$.


The MRR = Wdf_m where d = depth of cut.

FIGURE 20-6 Basics of milling processes (slab, face, and end milling) including equations for cutting time and metal removal rate (MRR).



Select cutting speed V , fpm and feed, f_r , in./rev. Select drill.
 D = diameter of the drill which rotates 2 cutting edges at rpm N_s . V = velocity of outer edge of the lip of the drill.
 $N_s = 12V/\pi D$. $T_m =$ cutting time = $(L + A)/f_r N_s$ where f_r is the feed rate in in. per rev. The allowance $A = D/2$.
 The MRR = $(\pi D^2/4)f_r N_s$ in.³/min which is approximately $3DVf_r$.


FIGURE 20-7 Basics of the drilling (hole-making) processes, including equations for cutting time and metal removal rate (MRR).



The T_m for broaching is $T_m = L/12V$. The MRR (per tooth) is $12tWV$ in.³/min where V = cutting velocity in fpm, W is the width of cut, t = rise per tooth.


FIGURE 20-8 Process basics of broaching. Equations for cutting time and metal removal rate (MRR) are developed in Chapter 26

FIGURE 20-9 (a) Basics of the shaping process, including equations for cutting time (T_m) and metal removal rate (MRR). (b) The relationship of the crank rpm N_s to the cutting velocity V .



The tool cuts at velocity V with a return velocity of V_R dictated by the rpm of the crank, N_s . The cutting speed $V = (I + A)N_s/12R_s$ where $R_s = \text{stroke ratio} = 200^\circ/360^\circ$ and the length of stroke is $I = L + \text{ALLOW}$. The tool feed is f_c inches per stroke.

$$T_m = W/N_s f_c$$

$$\text{MRR} = LdN_s f_c \text{ in}^3/\text{min}$$







Operation	Block diagram	Most commonly used machines	Machines less frequently used	Machines seldom used
Turning		Lathe NC lathe machining center	Boring mill	Turret lathe
Grinding		Cylindrical grinder		Lathe (with special attachment)
Sawing (of plates and sheets)		Contour or band saw	Laser Flame cutting Plasma arc	
Drilling		Drill press Machining center (nc) Vert. milling machine	Lathe Horizontal boring machine	Horizontal milling machine Boring mill
Boring		Lathe Boring mill Horizontal boring machine Machining center		Milling machine Drill press

FIGURE 20-10 Operations and machines used for machining cylindrical surfaces.




FIGURE 20-10 Operations and machines used for machining cylindrical surfaces.









Operation	Block diagram	Most commonly used machines	Machines less frequently used	Machines seldom used
Facing		Lathe	Boring mill	
Broaching		Broaching machine		Turret broach
Grinding		Surface grinder		Lathe (with special attachment)
Sawing		Cutoff saw	Contour saw	
Shaping		Horizontal shaper	Vertical shaper	
Planing		Planer		
Milling	slab milling 	Milling machine	Lathe with special milling tools	
	face milling 	Milling machine Machining center	Lathe with special milling tools	Drill press (light cuts)

FIGURE 20-11 Operations and machines used to generate flat surfaces.

20.3 Energy and Power in Machining

TABLE 20-2 Basic Machining Process

Applicable Process	Raw Material Form	Size		Typical Production Rate	Material Choice	Typical Tolerance	Typical Surface Roughness
		Maximum	Minimum				
Turning (engine lathes)	Cylinders, preforms, castings, forgings	78 in. dia. × 73 in. long	$\frac{1}{4}$ in. typical	1-10 parts/hour	All ferrous and nonferrous material considered machinable	±0.002 in. on dia. common; ±0.001 in. obtainable	125-250
Turning (CNC)	Bar, rod, tube, preforms	36 in. dia. × 93 in. long	$\frac{1}{4}$ in. dia.	1-2 parts/minute to 1-4 parts/hour	Any material with good machinability rating	±0.001 in. on dia. where needed; ±0.0005 in. possible	63 or better
Turning (automatic screw machine)	Bar, rod	Generally 2 in. dia. × 6 in. long	$\frac{1}{4}$ in. dia. and less, weight less than 1 ounce	10-30 parts/minute	Any material with good machinability rating ±0.001 to ±0.003 in.	±0.0005 in. possible ±0.001 to ±0.003 in. common	63 average
Turning (Swiss automatic machining)	Rod	Collets adapt to $\frac{1}{2}$ in. dia.	Collets adapt to less than $\frac{1}{2}$ in.	12-30 parts/minute	Any material with good machinability rating	±0.0002 in. to ±0.001 in. common	63 and better
Boring (vertical)	Casting, preforms	98 in. × 72 in.	2 in. × 12 in.	2-20 hours/piece	All ferrous and nonferrous	±0.0005 in.	90-250
Milling	Bar, plate, rod, tube	4-6 ft long	Limited usually by ability to hold part	1-100 parts/hour	Any material with good machinability rating	±0.0005 in. possible; ±0.001 in. common	63-250
Hobbing (milling gears)	Blanks, preforms, rods	10-ft dia. gears 14-in. face width	0.100 in. dia.	1 part/minute	Any material with good machinability rating	±0.001 in. or better	63
Drilling	Plate, bar, preforms	$3\frac{1}{2}$ -in.-dia. drills (1-in.-dia. normal)	0.002 in. drill dia.	2-20 second hole after setup	Any unhardened material; carbides needed for some case-hardened parts	±0.002-±0.010 in. common; ±0.001 in. possible	63-250
Sawing	Bar, plate, sheet	2-in. armor plate $\frac{1}{2}$ in. is preferred)	0.010 in. thick	3-30 parts/hour	Any nonhardened material;	±0.015 in. possible	250-1000
Broaching	Tube, rod, bar, plate	74 in. long	1 in.	300-400 parts/minute	Any material with good machinability rating	±0.0005-±0.001 in.	32-125
Grinding	Plate, rod, bars	36 in. wide × 7 in. dia.	0.020 in. dia.	1-1000 pieces/hour	Nearly all metallic materials plus many nonmetallic	0.0001 in. and less	16
Shaping	Bar, plate, casting	3 ft × 6 ft	Limited usually by ability to hold part	1-4 parts/hour	Low- to medium-carbon steels and nonferrous metals best; no hardened parts	±0.001-±0.002 in. (larger parts) ±0.0001-±0.0005 in. (small-medium parts)	63-250
Planing	Bar, plate, casting	42 ft wide × 18 ft high × 76 ft long	Parts too large for shaper work	1 part/hour	Low- to medium-carbon steels or nonferrous materials best	±0.001-±0.005 in.	63-125
Gear shaping	Blanks	120-in.-dia. gears 6-in. face width	1 in. dia.	1-60 parts/hour	Any material with good machinability rating	±0.001 in. or better at 200 D.P. to 0.0065 in. at 30 D.P.	63




FIGURE 20-12 Oblique machining has three measurable components of forces acting on the tool. The forces vary with speed, depth of cut, and feed.

3 Force

- F_C = Cutting force (vertical)
- F_R = Radial force (thrust)
- F_F = Feed force

TABLE 20-3 Values for Unit Power and Specific Energy (cutting stiffness)

Material		Unit Power (hp-min. in. ³) HP _s	Specific Energy (in.-lb/in. ³) K _s or U	Hardness Brinell HB
Nonalloy carbon steel	C 0.15%	.58	268,000	125
	C 0.35%	.58	302,400	150
	C 0.60%	.75	324,800	200
Alloy steel	Annealed	.50	302,400	180
	Hardened and tempered	0.83	358,400	275
	Hardened and tempered	0.87	392,000	300
	Hardened and tempered	1.0	425,000	350
High-alloy steel	Annealed	0.83	369,000	200
	Hardened	1.2	560,000	325
Stainless steel, annealed	Martensitic/ferritic	0.75	324,800	200
Steel castings	Nonalloy	0.62	257,000	180
	Low-alloy	0.67	302,000	200
	High-alloy	0.80	336,000	225
Stainless steel, annealed	Austenitic	0.73	369,600	180
Heat-resistant alloys	Annealed	0.78	—	200
	Aged—Iron based	—	—	280
	Annealed—Nickel or cobalt	1.10	—	250
	Aged	1.20	—	350
Hard steel	Hardened steel	1.4	638,400	55 HRC
	Manganese steel 12%	1.0	515,200	250
Malleable iron	Ferritic	0.42	156,800	130
	Pearlitic	—	257,600	230
Cast iron, low tensile		0.62	156,800	180
Cast iron, high tensile		0.80	212,800	260
Nodular SG iron	Ferritic	0.55	156,800	160
	Pearlitic	0.76	257,600	250
Chilled cast iron		—	492,800	400
Aluminum alloys	Non-heat-treatable	.25	67,200	60
	Heat-treatable	.33	100,800	100
Aluminum alloys (cast)	Non-heat-treatable	.25	112,000	75
	Heat-treatable	.33	123,200	90
Bronze-brass alloys	Lead alloys, Pb>1%	.25	100,800	110
	Brass, cartridge brass	1.8–2.0	112,000	90
	Bronze and lead-free copper	0.33–0.83	—	—
	Includes Electrolytic copper	0.90	246,400	100
Zinc alloy	Diecast	0.25	—	—
Titanium		.034	250-275	—

Values assume normal feed ranges and sharp tools. Multiply values by 1.25 for a dull tool.

Calculation of unit power (HP_s)

$$HP = F_c V / 33000$$


$$HP_s = HP / MRR \text{ Where}$$

$$MRR = 12Vfvc \text{ for tube turning}$$


$$HP_s = F_c V / (12Vfvc \times 33000) = F_c / fvc \times 396000$$

Calculation of specific energy (U)


$$U = F_c V / Vfvc = F_c / fvc \text{ for tube turning}$$



(a) OPM V (Front view) See Figure 21-14



(b) OTT (Top view) See Figure 21-15



(c) ODM (Top view)

FIGURE 20-13 Three ways to perform orthogonal machining. (a) Orthogonal plate machining on a horizontal milling machine, good for low-speed cutting. (b) Orthogonal tube turning on a lathe; high-speed cutting (see Figure 20-16). (c) Orthogonal disk machining on a lathe; very high-speed machining with tool feeding (ipr) in the facing direction

20.4 Orthogonal Machining (Two Forces)




FIGURE 20-14 Schematics of the orthogonal plate machining setups. (a) End view of table, quick-stop device (QSD), and plate being machined for OPM. (b) Front view of horizontal milling machine. (c) Orthogonal plate machining with fixed tool, moving plate. The feed mechanism of the mill is used to produce low cutting speeds. The feed of the tool is t and the DOC is w , the width of the plate.




FIGURE 20-15 Orthogonal tube turning (OTT) produces a two-force cutting operation at speeds equivalent to those used in most oblique machining operations. The slight difference in cutting speed between the inside and outside edge of the chip can be neglected.





FIGURE 20-16
 Videograph
 made from the
 orthogonal plate
 machining process.

FIGURE 20-17 Schematic representation of the material flow, that is, the chip-forming shear process. f defines the onset of shear or lower boundary. c defines the direction of slip due to dislocation movement.






FIGURE 20-18 Three characteristic types of chips. (Left to right) Discontinuous, continuous, and continuous with built-up edge. Chip samples produced by quick-stop technique. (Courtesy of Eugene Merchant (deceased) at Cincinnati Milacron, Inc., Ohio.)

20.5 Merchant's Model





FIGURE 20-19 Velocity diagram associated with Merchant's orthogonal machining model.

20.6 Mechanics of Machining (Statics)

FIGURE 20-20 Free-body diagram of orthogonal chip formation process, showing equilibrium condition between resultant forces R and R' .






FIGURE 20-21 Merchant's circular force diagram used to derive equations for F_s , F_r , F_t , and N as functions of F_c , F_r , f , a , and b .

20.7 Shear Strain and Shear Front Angle

FIGURE 20-22 Shear stress τ_s variation with the Brinell hardness number for a group of steels and aerospace alloys. Data of some selected fcc metals are also included. (Adapted with permission from S. Ramalingham and K. J. Trigger, *Advances in Machine Tool Design and Research*, 1971, Pergamon Press.)






FIGURE 20-23 The Black–Huang “stack-of-cards” model for calculating shear strain in metal cutting is based on Merchant’s bubble model for chip formation, shown on the left.




Merchant's bubble model of chip formation



Black-Huang stack-of-cards model

The shaded shear triangle on the right is used to develop the basic equation for shear strain, γ .



20.8 Mechanics of Machining (Dynamics)






FIGURE 20-24 Machining dynamics is a closed-loop interactive process that creates a force-displacement response.

- **Free Vibration** The response to an initial condition or sudden change. The amplitude of the vibration decreases with time and occurs at the natural frequency of the system often produced by interrupted machining. Often appears as lines or shadows following a surface discontinuity.



- **Forced Vibration** The response to a periodic (repeating with time) input. The response and input occur at the same frequency. The amplitude of the vibration remains constant for a set input condition and is nonlinearly related to speed. Unbalance, misalignment, tooth impacts, and resonance of rotating systems are the most common examples.



- **Self-Excited Vibration** The periodic response of the system to a constant input. The vibration may grow in amplitude (unstable) and occurs near the natural frequency of the system regardless of the input. Chatter due to the regeneration of surface waviness is the most common metal cutting example.




FIGURE 20-25
There are three types of vibration in machining.

FIGURE 20-26 Some examples of chatter that are visible on the surfaces of the workpiece.





FIGURE 20-27 When the overlapping cuts get out of phase with each other, a variable chip thickness is produced, resulting in a change in F_c on the tool or workpiece.






FIGURE 20-28 Regenerative chatter in turning and milling produced by variable uncut chip thickness.





FIGURE 20-29 Milling and boring operations can be made more stable by correct selection of insert geometry.

FIGURE 20-30 Dynamic analysis of the cutting process produces a stability lobe diagram, which defines speeds that produce stable and unstable cutting conditions.






FIGURE 20-31 Distribution of heat generated in machining to the chip, tool, and workpiece. Heat going to the environment is not shown. Figure based on the work of A. O. Schmidt.




FIGURE 20-32 There are three main sources of heat in metal cutting. (1) Primary shear zone. (2) Secondary shear zone tool–chip (T–C) interface. (3) Tool flank. The peak temperature occurs at the center of the interface, in the shaded region.




FIGURE 20-33 The typical relationship of temperature at the tool–chip interface to cutting speed shows a rapid increase. Correspondingly, the tool wears at the interface rapidly with increased temperature, often created by increased speed.

20.9 Summary