





# Two materials that are completely insoluble in each other in both the liquid and solid states




# Cooling curves of H<sub>2</sub>O & NaCl mixtures



**Figure 4-3** Cooling curves for five different solutions of salt and water: a) 0% NaCl; b) 10% NaCl; c) 23.5% NaCl; d) 50% NaCl; e) 100% NaCl.


# Cooling Curves

- Figure 4-4 shows the transition points of a temperature time curve for a solution of NaCl in water
- Line a-c-f-h-l shows the lowest temperature at which the solution is totally liquid, known as a liquidus line




**Figure 4-4** Partial equilibrium diagram for NaCl and H<sub>2</sub>O derived from cooling-curve information.

# Solubility Diagrams




**Figure 4-6 (Below)** Copper-nickel equilibrium phase diagram, showing complete solubility in both liquid and solid states.


# Pb-Sn diagram




# Three-phase reactions




Eutectic  
( $L \rightarrow S_1 + S_2$ )




Peritectic  
( $L + S_1 \rightarrow S_2$ )




Monotectic  
( $L_1 \rightarrow S_1 + L_2$ )




Syntectic  
( $L_1 + L_2 \rightarrow S_1$ )




Eutectoid  
( $S_1 \rightarrow S_2 + S_3$ )



Peritectoid  
( $S_1 + S_2 \rightarrow S_3$ )




Stoichiometric  
intermetallic compound



Nonstoichiometric  
intermetallic compound

**Figure 4-9** Schematic summary of three-phase reactions and intermetallic compounds.

# Iron-Carbon Equilibrium Diagram



**Figure 4-10** The iron-carbon equilibrium phase diagram. Single phases are  $\alpha$ , ferrite;  $\gamma$ , austenite;  $\delta$ ,  $\delta$ -ferrite;  $\text{Fe}_3\text{C}$ , cementite.


- Four single phase solids within the diagram
- Delta-ferrite, austenite, ferrite, cementite
- Steels are the iron alloys with less than 2.11% carbon



# Utilization of Diagrams

Figure 4/8 Equilibrium diagram showing the changes that occur during the cooling of an alloy X.

- Phase diagrams contain the following information
  - The phases that are present at a given temperature and composition
  - Composition of each phase
  - Amount of each phase present
    - Using the lever law, the amount of each phase in a two-phase region can be calculated



Fraction of the material that is liquid

$$\frac{a - S_2}{L_2 - S_2} \times 100\% = L.F.$$

# Fe-C Low T, Low 5C

