


TOLERANCES AND ALLOWNANCES


Accuracy Versus Precision in Processes




(a) Accurate and precise



(b) Precise, not accurate



(c) Accurate, not precise



(d) Precise within sample
Not precise between samples
Not accurate overall or within sample

- Accuracy- ability to hit what is aimed at
- Precision- repeatability of the process
- Measuring devices must be both precise and accurate
- Skill of the operator may also have to be taken into account for measurements

Figure 10-6 Accuracy versus precision. Dots in targets represent location of shots. Cross (X) represents the location of the average positions of all shots.

MEAN VALUE

$$\mu = \frac{\sum_{i=1}^n X_i}{n}$$

- X_i -measurement i
- n -total number of measurements
- μ -mean value

STANDARD DEVIATION

$$\sigma = \sqrt{\frac{\sum_{i=1}^n (X_i - \mu)^2}{n}}$$

Tolerances

- A ***tolerance*** is an acceptable amount of dimensional variation that will still allow an object to function correctly.
- Tolerance- undesirable but permissible deviation from a desired dimensions
 - No part can be made exactly to a specified dimension
 - Necessary to permit the actual dimension to deviate from the theoretical (nominal) dimension

TOTAL TOLERANCE

- The total tolerance is a value that describes the maximum amount of variation.
- Tolerance = $\pm .010$
- **.500**
- **.020**
- **.490**
- **.510**

NATURAL TOLERANCE LIMITS

- Upper (UNTL) and Lower (LNLT) natural tolerance limits

$$\mu + 3\sigma = UNTL$$

$$\mu - 3\sigma = LNLT$$

Specifying Tolerance

- Tolerance can be specified in four ways
 - Bilateral, unilateral, limits and geometric
- Bilateral
 - Plus or minus deviation from the nominal size
- Unilateral
 - Deviation is in one direction from the nominal size
- Limits
 - Maximum and minimum dimensions

Bilateral Tolerance

- A ***bilateral tolerance*** exists if the variation from a target dimension is shown occurring in both the positive and negative directions

SPECIFYING TOLERANCES:BILETERAL

$10.0\text{mm}^{+0.1\text{mm}}_{-0.2\text{mm}}$

$3.000\text{in}^{+0.002\text{in}}_{-0.004\text{in}}$

Unilateral Tolerance

-
- A ***unilateral tolerance*** exists when a target dimension is given along with a tolerance that allows variation to occur in only one direction.

SPECIFYING TOLERANCES: UNILETERAL

$10.0\text{mm}^{0.0}_{-0.1}$

$3.000\text{in}^{0.000\text{in}}_{-0.002\text{in}}$

Limit Dimensions

-
- ***Limit dimensions*** are two dimensional values stacked on top of each other. The **dimensions** show the largest and smallest values allowed. Anything in between these values is acceptable.

Limit Dimensions

- **500-target dimension**
- **.020-total tolerance**
- **.490**
- **.510**

UNSPECIFIED TOLERANCES

- If no tolerances are specified at the dimension level, then general tolerances may be applied by deliberately controlling the number of values past the decimal point on each dimension.

A measuring device

- A measuring device should be able to accurately measure within 1/10th of the total blueprint tolerance identified.

Geometric Tolerances


- Maximum allowable deviation of a form or position from the perfect geometry
- Maximum material condition indicates that a part is made with the maximum allowable material
- Least material condition indicates that a part is made with the minimum allowable material
- Geometric tolerances are specified with respect to a datum or reference surface
- Four tolerances
 - Flatness, straightness, roundness, and cylindricity

Geometric Tolerances


	Tolerance	Characteristic	Symbol
Individual features	Form	Straightness	—
		Flatness	
		Circularity	
		Cylindricity	
Individual or related features	Profile	Line	
		Surface	
Related features	Orientation	Angularity	
		Perpendicularity	
		Parallelism	
	Location	Position	
		Concentricity	
	Runout	Runout	Circular runout
Total runout			

Notes				
	DIA	MMC	LMC	RFS

(a)




(b)



Tolerance specification

(c)



Interpretation

(d)

Figure 10-11 (a) Geometric tolerancing symbols; (b) feature control symbols for part drawings; (c) how a geometric tolerance for flatness is specified; (d) what the specification means.

10.3 Allowance and Tolerance

- Allowance- intentional, desired difference between two mating parts
 - Determines the condition of tightest fit
 - May be specified for clearance or interference
- Tolerance- undesirable but permissible deviation from a desired dimensions

Allowance and Tolerance





Figure 10-7 When mating parts are designed, each shaft must be smaller than each hole for a clearance fit.


Three Types of Fit

- There are three types of fit that should be considered when working with tolerances.
- Clearance Fit- have limits of size so prescribed that a clearance always results when mating parts are assembled.
- Interference Fit- have limits of size so prescribed that an interference always results when mating parts are assembled.
- Transition Fit- have limits of size indicating that either a clearance or an interference may result when mating parts are assembled.


SHAFT VS HOLE



(a) Basic size, deviation and tolerance in the ISO system.



(b) Shaft-basis and hole-basis system for specifying fits in the ISO system.





(c) Position of the various tolerance zones for a given diameter in the ISO system.

ANSI Classes of Fits

- Class 1: Loose fit
- Class 2: Free fit
- Class 3: Medium fit
- Class 4: Snug fit
- Class 5: Wringing fit
- Class 6: Tight fit
- Class 7: Medium force
- Class 8: Heavy force and shrink fits

ISO System of Limits and Fits

- Used in metric countries
- Each part has a basic size and each limit is defined by its limit from that size
 - Difference is called the tolerance
- Three classes of fits
 - Clearance
 - Transition
 - Interference
- Tolerances may be specified with respect to zero deviation



Testing

- Destructive testing
 - Components are subjected to conditions to induce failure
- Proof testing
 - Product is subjected to a load or pressure of some known and determined magnitude to simulate product life
- Hardness tests
- Nondestructive testing
 - Products are examined in a way that it can still be used

Dormant versus Critical Flaws

- Most materials have flaws of some magnitude
- The extent and possible severity of flaws is important in determining if the flaws in the product can be tolerated
- Larger defects may grow or propagate under cyclic loading
- Identify the conditions below which the flaw remains dormant and above which it becomes critical

Summary

- Measurement and inspection is an important aspect of quality control
- There is a wide variety of techniques that can be employed to make measurements
- The correct technique depends on the application, available equipment, and necessary accuracy
- Cost may play a role in determining which technique is appropriate