

# FUNDAMENTALS OF METAL ALLOYS, EQUILIBRIUM DIAGRAMS

## Chapter 5

## 5.2 What is a Phase?

- **Phase** is a form of material having characteristic structure and properties.
- More precisely: form of material with **identifiable composition (chemistry)**, **definable structure**, and **distinctive boundaries (interfaces)** which separate it from other phases.


# 5.2 Phases

- Phase can be continuous (air in the room) or discontinuous (salt grains in the shaker).
- Gas, liquid or solid.
- Pure substance or solution ( uniform structure throughout).




# 5.3 Equilibrium Phase Diagrams

- Graphic mapping of the natural tendencies of a material or a material system (equilibrium for all possible conditions).
- Primary variables: temperature, pressure and composition.
- P-T diagram (the simplest).




# 5.3 Temperature-Composition Diagrams

- Engineering processes conducted at atmospheric pressure (P/T variations).
- The most common: temperature-composition phase diagrams.




# 5.3 Cooling Curves

- Cooling curves for NaCl-H<sub>2</sub>O combinations:



## 5.3 Cooling Curves

- Partial equilibrium diagram of NaCl-H<sub>2</sub>O system




## 5.3 Solubility

- Solubility limits.
- Degree of solubility determines properties.
- I-Two metals completely soluble in each other.
- II- Two metals soluble in liquid state and insoluble in solid state.
- III-Two metals soluble in liquid state and partially soluble in solid state.




## 5.3 Complete Solubility

- Copper-Nickel equilibrium diagram



## 5.3 Partial Solid Solubility




- Degree of solubility depends on temperature
- At max. solubility, 183°C: lead holds up to 19.2 wt% tin in a single phase solution, and tin holds up to 2.5wt% lead and still be a single phase.

## 5.3 Utilization of Diagrams

$$\text{Liquid phase amount} = \frac{a - S_2}{L_2 - S_2} \times 100\% = \% \text{ by mass}$$

$$\text{Solid phase amount} = \frac{L_2 - a}{L_2 - S_2} \times 100\% = \% \text{ by mass}$$



## 5.3 Example problem

*Given data :*


$X = 36\%$  of  $B$

$a = 36\%$  of  $B$

$L_2 = 72\%$  of  $B$

$S_2 = 18\%$  of  $B$

*Compute liquid phase and solid phase  
% amounts by mass.*




$$\text{Liquid phase amount} = \frac{36 - 18}{72 - 18} \times 100\% = 33.33\% \text{ by mass}$$

$$\text{Solid phase amount} = \frac{72 - 36}{72 - 18} \times 100\% = 66.67\% \text{ by mass}$$


## 5.3 Utilization of Diagrams

- The phases present.
- Composition of each phase ( single phase region or two phase region).
- In two phase region a **tie-line** should be constructed.
- The amount of each phase present: **lever-law** calculation using a tie-line.


# 5.3 Three Phase Reactions




**Eutectic**  
( $L \rightarrow S_1 + S_2$ )




**Peritectic**  
( $L + S_1 \rightarrow S_2$ )




**Monotectic**  
( $L_1 \rightarrow S_1 + L_2$ )




**Syntectic**  
( $L_1 + L_2 \rightarrow S_1$ )




**Eutectoid**  
( $S_1 \rightarrow S_2 + S_3$ )



**Peritectoid**  
( $S_1 + S_2 \rightarrow S_3$ )



**Stoichiometric**  
intermetallic compound



**Non-stoichiometric**  
intermetallic compound

# Intermetallic Compounds

- If two components in a compound can only exist at one atomic ratio, the compound is known as a stoichiometric intermetallic compound
- Appears as a single vertical line in the equilibrium phase diagram
- If some degree of variability is tolerable, then the vertical line will extend into a single phase region

# 5.4 Iron-Carbon Equilibrium Diagram

4 Single Phase solids:  
• 3 in pure Fe and one Fe-carbide inter-metallic


$\alpha$ , ferrite (BCC)

$\gamma$ , austenite (FCC)

$\delta$ ,  $\delta$ -ferrite (BCC)

$\text{Fe}_3\text{C}$ , cementite (6.67% C)

Curie po. nonmagnetic to  
magnetic transition





## 5.4 Iron-Carbon Equilibrium Diagram

- $\delta$  – *ferrite* (present only at extreme temperatures)
- **Austenite**, (FCC, high formability, high solubility of C, over 2% C can be dissolved in it, most of heat treatments begin with this single phase).
- **Ferrite**, BCC, stable form of iron below 912 deg.C, only up to 0.02 wt% C in solid solution and leads to two phase mixture in most of steels.
- **Cementite** (iron-carbide), stoichiometric intermetallic compound, hard, brittle, exact melting point unknown.
- **Currie point** (770 deg. C), atomic level nonmagnetic-to-magnetic transition.

# 5.4 Key Points of Fe-C Diagram

Phases:

- Liquid Fe-T-min=1148C @ 4.3%C
- 1394 C <  $\delta$ -Fe < 1538C
- $\alpha$ -Ferrite (Ferrite) < 912C; < 0.02%C
- Magnetic-nonmagnetic-770C
- Cementite  $Fe_3C$ =6.67weight %C
- Austenite-727 C < T < 1495 C; 0 < %C < 2.11

# 5.4 Phase Transformations

## Liquid to Austenite

- Eutectic transformation-1148C,
- C-2.11%-4.3%
- Eutectic transformation-4.3% C, 1148C
- Eutectic transformation  $L-\gamma+Fe_3C$  (fast)
- Eutectic trans  $L-\gamma+C$  (graphite) (slow)


# 5.4 Eutectoid Transformation

- $\gamma \rightarrow$  pearlite (ferrite +  $Fe_3C$ )
- 727 C, 0.77 % C eutectic point


## 5.4 Three Phase Reactions

- **Peritectic**, at 1495 deg.C, with low wt% C alloys (almost no engineering importance).
- **Eutectic**, at 1148 deg.C, with 4.3wt% C, happens to all alloys of more than 2.11wt% C and they are called **cast irons**.
- Eutectoid, at 727 deg.C with eutectoid composition of 0.77wt% C, alloys below 2.11%C miss the eutectic reaction to create two-phase mixture. They are **steels**.


# 5.4 Iron-Carbon Equilibrium Diagram



# 5.4 Iron-Carbon Equilibrium Diagram



# 5.4 Iron-Carbon Equilibrium Diagram




$$\% \text{ Austenite} = \frac{6.67 - 3}{6.67 - 1.75} \times 100\% = 74.74\% \text{ by mass}$$



## 5.5 Steels and the Simplified Iron-Carbon Diagram

- Steels having less than the eutectoid amount of carbon are hypoeutectoid steels
- Steels having more than the eutectoid amount of carbon are called hypereutectoid steels
- Transitions occur both in slow heating and cooling

# 5.5 Steels



*Austenite*  $_{0.77\% C; FCC} \rightarrow$  *Ferrite*  $_{0.02\% C; BCC} +$  *Cementite*  $_{6.67\% C}$


# 5.5 Eutectoid Steel

- At 0.77%C by cooling from austenite (FCC) changes to BCC-ferrite (max 0.02%C) and excess C forms intermetallic cementite.
- Chemical crystalline solid separation gives fine mixture of ferrite and cementite. Pearlite (right), 1000X.






# Medium Carbon Steel





# Low Carbon Steel



## 5.5 Pearlite

- **Pearlite** is a two-phased, lamellar (or layered) structure composed of alternating layers of alpha-ferrite(88 wt%) and cementite(12%) that occurs in some steels and cast irons.
- It forms by a eutectoid reaction as austenite is slowly cooled below 727C.
- The eutectoid composition of Austenite is approximately 0.8% carbon[1];.


## 5.5 Pearlite

- Steel with less carbon content will contain a corresponding proportion of relatively pure ferrite crystallites that do not participate in the eutectoid reaction and cannot transform into pearlite.
- Steel with more carbon content will contain a corresponding proportion of relatively pure cementite crystallites that do not participate in the eutectoid reaction and cannot transform into pearlite
- Hypo-vs Hypereutectoid steels



# 5.5 Hypoeutectoid Steel


- With less than 0.77% C from austenite by cooling transformation leads to growth of low-C ferrite growth. At 727deg.C austenite transforms into pearlite.
- Mixture of **proeutectoid ferrite** (white) and regions of **pearlite** forms.
- Magnification 500X.






# 5.5 Hypereutectoid Steel

- With more than 0.77% C, from austenite transformation leads to proeutectoid primary cementite and secondary ferrite. At 727 deg. C austenite changes to pearlite
- Structure of primary **cementite** and **pearlite** forms.
- Magnification 500X.




# 5.6 Cast Irons

- Iron-Carbon alloys of 2.11%C or more are cast irons.
- Typical composition: 2.0-4.0%C, 0.5-3.0% Si, less than 1.0% Mn and less than 0.2% S.
- Si-substitutes partially for C and promotes formation of graphite as the carbon rich component instead Fe<sub>3</sub>C.




# 5.6 Gray Cast Iron

- Composes of: 2.5-4.0% C, 1.0-3.0% Si and 0.4-1.0% Mn.
- Microstructure: 3-D graphite flakes formed during eutectic reaction. They have pointed edges to act as voids and crack initiation sites.
- Sold by class (class 20 has min. tensile strength of 20,000 psi is a high C-equivalent metal in ferrite matrix ). Class 40 would have pearlite matrix.





## 5.6 Gray Cast Iron with Lamellar Graphite



## 5.6 Gray Cast Iron


- Properties: excellent compressive strength, excellent machinability, good resistance to adhesive wear (self lubrication due to graphite flakes), outstanding damping capacity ( graphite flakes absorb transmitted energy), good corrosion resistance and it has good fluidity needed for casting operations.
- It is widely used, especially for large equipment parts subjected to compressive loads and vibrations.

## 5.6 White Cast Iron

- Composes of: 1.8-3.6% C, 0.5-1.9% Si and 0.25-0.8% Mn.
- All of its carbon is in the form of iron-carbide ( $\text{Fe}_3\text{C}$ ). It is called white because of distinctive white fracture surface.
- It is very hard and brittle (a lot of  $\text{Fe}_3\text{C}$ ).
- It is used where a high wear resistance is dominant requirement (coupled hard martensite matrix and iron-carbide). Thin coatings over steel (mill rolls).




## 5.6 White Cast Iron



## 5.6 Malleable Cast Iron

- Formed by extensive heat treatment around 900 deg C,  $\text{Fe}_3\text{C}$  will dissociate and form irregular shaped graphite nodules. Rapid cooling restricts production amount to up to 5 kg. Less voids and notches.
- Ferritic MCI: 10% EL, 35 ksi yield strength, 50 ksi tensile strength. Excellent impact strength, good corrosion resistance and good machinability.






## 5.6 Pearlitic Malleable Cast Iron

- Pearlitic MCI: by rapid cooling through eutectic transformation of austenite to pearlite or martensite matrix.
- Composition: 1-4% EL, 45-85 ksi yield strength, 65-105 ksi tensile strength. Not as machinable as ferritic malleable cast iron.

# Ductile Cast Iron


- Without a heat treatment by addition of ferrosilicon ( $\text{MgFeSi}$ ) formation of smooth spheres (nodules) of graphite is promoted.
- Properties: 2-18% EL, 40-90 ksi yield strength, 60-120 ksi tensile strength.
- Attractive engineering material due to: good ductility, high strength, toughness, wear resistance, machinability and low melting point castability.

# Nodular Graphite with Ferritic Matrix




## 5.6 Malleable Cast Iron

- Ductile iron with ferrite matrix (top) and pearlite matrix (bottom) at 500X.
- Spheroidal shape of the graphite nodule is achieved in each case.





# Microstructure




- Globular cast iron

# Summary

- Phase diagrams can be used to predict how materials will behave during different heat treating processes
  - Diagrams are used extensively in casting processes to predict needed cooling rates
- Cast irons are specifically used for casting
- Properties of cast irons differ from those of other iron compounds

# BCC Unit Cell



# FCC Unit Cell

